

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	4160	134/2,2,26,902.ccls.	USPAT	2007/02/02 15:52
2	BRS	L2	0	1 and ("p-dope" or "N-dope")	USPAT	2007/02/02 15:52
3	BRS	L4	0	3 and supercritical	USPAT	2007/02/02 15:56
4	BRS	L5	30121	"134"/\$.ccls.	USPAT	2007/02/02 15:56
5	BRS	L6	275	5 and supercritical	USPAT	2007/02/02 15:56
6	BRS	L7	0	6 and ("p-doped" or "N-doped")	USPAT	2007/02/02 15:57
7	BRS	L8	8360	("p-doped" or "N-doped")	USPAT	2007/02/02 15:57
8	BRS	L9	44	8 and supercritical	USPAT	2007/02/02 15:58
9	BRS	L10	0	9 and "134"/\$.ccls.	USPAT	2007/02/02 15:58
10	BRS	L12	0	11 and galvanic	USPAT	2007/02/02 15:59
11	BRS	L13	6	11 and corrosion	USPAT	2007/02/02 15:59
12	BRS	L3	2	1 and ("p-doped" or "N-doped")	USPAT	2007/02/02 16:02
13	BRS	L11	32	9 and (removing or cleaning)	USPAT	2007/02/02 16:03